MEMO TO FILE

The following information,	Photos	, has been
separated from the rest of the		
site, Schree-Morehead Ch	OMID # TXDOO73	334659 , because
the material could not be sto	red at the Federal	Records Center due
to certain storage restriction	ns.	

9525702

Photographer / Witness

Barry Nash

Date / Time / Direction

2-27-81 /1020/ NNE

comments: Drum Storage on north Side of plant near railroad tracks. Note that drums are on pallets for easy movement.

PHOTO 1-2



PHOTO 3



Photographer / Witness


Barry Nash

Date / Time / Direction

2-27-81/1024/ W

side of property. Note drainage conduits in cement slab.







Photographer / Witness

Barry Mash

Date / Time / Direction

2-27-81/1035/NW

Comments: Drum storage on

West side of plant property



PHOTO 6
Photographer / Witness

Bary Mash

Date / Time / Direction

10 2-27-81/1040/CLOSEUP

Comments: Leakage from drum.

Powdered calcium carbonate

(Caloz) is spread on spill to help

congeal the material, which

is then scraped up.





F o 7
Photographer / Witness
Barry Nash
Date / Time / Direction
2-27-81/1045/ CLOSEUP
Comments: Leakage from drums.
As material comes in contact
with air, solvent evaporates and
the material turns to a
rubbery consistency. Spills do
rubbery consistency. Spills do not travel far.
PHOTO 8 Photographer / Witness
Barry Nach
Date / Time / Direction
2-27-81/1055/ NNE
comments: Drum storage on
west side of plant
property. Fenced area
to left is Koppers Paints.
Photographer / Witness
Date / Time / Direction

Photo	ogr	apher	- / V	Vitne	ess	
Date	1	Time	/ Di	irect	ion	
Comme	ent	:s:				